
From: Kenneth Roller (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=KENNE64]
Sent: 5/5/2015 2:44:42 PM
To: Cathy C Taylor (Services - 6) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Cathy25]
Subject: FW: Ash Pond ABC inspection 04/27/15
Attachments: 20150505114648357.pdf

Fyi.

From: Jeffrey R Marcell (Generation - 3)
Sent: Tuesday, May 05, 2015 1:26 PM
To: Michael J Winters (Generation - 34)
Cc: John Cima (Generation - 34); Jeffrey C Heffelman (Generation - 3); Kenneth Roller (Services - 6)
Subject: RE: Ash Pond ABC inspection 04/27/15

Attached.

No Discharge at C Pond. Standing water around weir and Southeastern edge of Pond C and into center of C Pond. Some water is entering the pipe inside the weir but the water at the discharge end of C Pond is stagnant and no flow detected. Ponded water around discharge pipe at Creek from tidal activity makes it difficult to ascertain discharge.

Some seeping and dripping inside C Pond discharge weir about 7' down from top below wooden brace installed by Crofton.

Standing water behind sand-bags at 'A' with standing water at the toe of the slope and flow under bags into rip-rap. The southern edge of the 'A' pond interior, from the SE corner to the sandbags, continues to hold water. The NE end of A Pond is holding water in pathway created from matting/equipment activity, noticeable depression in this section from activity related to drilling.

No standing water behind sand-bags at 'B' pond.

No precipitation in the last 72hrs.

Let me know if you have any questions.

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)